

Firmware Change History for TM-m30II

| Version | Category | Detail |
|----------------------------------|------------------|--|
| 02.03A ESC/POS 02.03B ESC/POS | New Release | - |
| 02.04A ESC/POS 02.04B ESC/POS | Changed function | Added "signature" and "serialNumber" parameters as an output parameter of GetLastTransactionResponse. This affects only the German Fiscal function. |
| | Bug fix | Fixed a bug that there is a setting value that cannot be restored the recovery point with "Restore&Delete" in the panel operation. (TM-m30II: Ver.02.03 ESC/POS) |
| | | Fixed a bug below: In ePOS-Device, if one or more devices are connected to the printer, DEVICE_IN_USE is not resolved when returning the disconnect event from the client application immediately after executing createDevice. |
| 02.06A ESC/POS 02.06B ESC/POS | Bug fix | Fixed a bug that the print position of image data printed in the page mode of the ePOS-SDK is out of alignment. |
| | | Fixed a bug that the Export function cannot be executed if TSE's certificate is expired. This affects only the German Fiscal function. |
| 02.07A ESC/POS 02.07B ESC/POS | Bug fix | Fixed a bug that ERROR_IO or SIG_ERROR may be returned from TSE. This affects only the German Fiscal function. |
| 02.08A ESC/POS 02.08B ESC/POS | Function change | Supported OT-WL06 in some regions (CIS, MEA) |
| | Bug fix | Fixed a bug that unable to connect to WPA2 Enterprise APs using RADIUS servers that do not support TLS 1.0. |
| | | Fixed a bug that the page mode area and the line spacing are changed when specifying "mul" as the lang attribute to the text tag on ePOS-Print. |
| 02.10A ESC/POS 02.10B ESC/POS | Bug fix | Fixed a bug that, if the cover is opened during the cutting operation, the cover may not be closed. |
| 02.12A ESC/POS 02.12B ESC/POS | Function change | Improved a connectivity to AP (SSID is in the stealth mode) with W53/W56 when using OT-WL06. |

* Ver.**.**B ESC/POS supports OT-WL05 and OT-WL06.

Firmware Change History for TM-m30II-H, TM-m30II-NT, TM-m30II-S, and TM-m30II-SL

| Version | Category | Detail |
|--|------------------------|---|
| 03.03A ESC/POS 03.03B ESC/POS *Only for TM-m30II-H | New Release | - |
| 03.04A ESC/POS 03.04B ESC/POS *Only for TM-m30II-H | Changed function | Added "signature" and "serialNumber" parameters as an output parameter of GetLastTransactionResponse. This affects only the German Fiscal function. |
| | Fixed bug | Fixed a bug that there is a setting value that cannot be restored the recovery point with "Restore&Delete" in the panel operation. (TM-m30II-H: Ver.03.03 ESC/POS) Fixed a bug below: In ePOS-Device, if one or more devices are connected to the printer, DEVICE_IN_USE is not resolved when returning the disconnect event from the client application immediately after executing createDevice. |
| 03.05A ESC/POS 03.05B ESC/POS | Updated support model | Supported TM-m30II-NT and TM-m30II-S. |
| | Fixed bug | Fixed a bug that the setting values are cleared when unplugging the power cable about 25 seconds after the printer is turned on. |
| 03.06A ESC/POS 03.06B ESC/POS | Fixed bug | Fixed a bug that the print position of image data printed in the page mode of the ePOS-SDK is out of alignment. |
| | | Fixed a bug that the Export function cannot be executed if TSE's certificate is expired. This affects only the German Fiscal function. |
| 03.07A ESC/POS 03.07B ESC/POS | Fixed bug | Fixed a bug that ERROR_IO or SIG_ERROR may be returned from TSE. This affects only the German Fiscal function. |
| 03.08A ESC/POS 03.08B ESC/POS | Function change | Supported OT-WL06 in some regions (CIS, MEA) |
| | Bug fix | Fixed a bug that unable to connect to WPA2 Enterprise APs using RADIUS servers that do not support TLS 1.0. |
| | | Fixed a bug that the page mode area and the line spacing are changed when specifying "mul" as the lang attribute to the text tag on ePOS-Print. |
| | | Fixed a bug that the cloud information cannot be got via WebConfig API. |
| Updated support model | Supported TM-m30II-SL. | |
| 03.09A ESC/POS 03.09B ESC/POS | Bug fix | Fixed a bug that the firmware version of the sub-microcomputer may not be obtained. |
| 03.10A ESC/POS 03.10B ESC/POS | Bug fix | Fixed a bug that, if the cover is opened during the cutting operation, the cover may not be closed. |
| 03.11A ESC/POS 03.11B ESC/POS | Function change | Changed the power supply spec for Device Charging Port. |
| 03.12A ESC/POS 03.12B ESC/POS | Function change | Improved a connectivity to AP (SSID is in the stealth mode) with W53/W56 when using OT-WL06. |

* Ver.**.**A ESC/POS supports OT-WL02 and OT-WL06.

* Ver.**.**B ESC/POS supports OT-WL05 and OT-WL06.