

Firmware Change History for BA-T500II

Version	Category	Detail
10.07	Changed function	Measures to prevent missing dots caused by Over energy.
		Added support for new ROM to deal with EOL of the current
	Fixed bug	Fixed a bug that QR codes/graphics are printed in mangled