

Firmware Change History for TM-T82III (Ethernet models)

Version	Category	Detail
20.02 ESC/POS	-	New Release
20.03 ESC/POS	Changed function	Added models for the OT-WL06.
		Changed default password for WebConfig access from "epson" to the serial number of the printer to comply with the regulations (Chapter 886) in California, U.S.
20.03 ESC/POS	Bug fix	Changed contents of the self-signed certificate to comply with the iOS 13 specifications
		Fix a bug that this product cannot print by ePOS-Print when using this product as a network printer from an intelligent printer (like a TM-T88VI-iUIB).
20.04 ESC/POS	Changed function	Added SKU for the OT-WL06
		Improved a connectivity to AP (SSID is in stealth mode) with W53/W56 when using OT-WL06.
		Changed the SNMP packet processing during the power saving mode.
	Bug fix	Fixed a bug that recovery point cannot be restored by "Restore&Delete" operation.
		Fixed a problem that the position is shifted from the middle of the image with ePOS Print.
		Fixed a problem that the network response time slows down when a large amount of UDP packets is received at startup.
20.05 ESC/POS	Updated support model/OS	Added support for Windows 11.
		End of support for Windows 8 and Windows 8.1.
	New function	The models have complied with the UK's PSTI bill.
		Added a function in ePOS-Print to support the change in specifications (change in the initial setting value) of Private Network Access starting with Chrome 105.
	Bug fix	*The following problems occur only when SNMP packets that are not supported by the printer are sent periodically. Fixed a bug that caused processing to stop during the transition to power-saving mode, making the printer unable to communicate and print.