

Firmware Change History for TM-m10 for Americas

Version	Category	Detail
3.12 ESC/POS	Added new function	Added setting item of "Wellknown Community Name" on EpsonNet Config Web version.
	Changed function	Disabled "TLS1.0/1.1" for HTTPs in case of the "Encryption Strength" setting is set to "High".
		Changed to process ENPC 03-0021 (status request) during power saving.
	Bug fix	Fixed Vulnerability of WPA2 (OT-WL02)
Fixed a bug that Port 9100 connection may become impossible.		
Fixed a bug that LPR printing is interrupted.		
3.14A ESC/POS 3.14B ESC/POS	Added new function	Added support for OT-WL06.
	Changed function	Removed a "crossdomain.xml" file to reduce a potential security risk.
		Improved the operation log function.
	Bug fix	If a printer cannot shift to the first power saving mode after power supply ON or reset, the printer is reset.
		Fixed a bug that the printer error may occur after a specific Android device which is connected via USB restarted.
		Fixed a bug that the printer may not respond when repeatedly switching to/from the information acquisition mode.
		Fixed a bug that cannot print after a timeout occurred in the ePOS-Print.
		Fixed a bug that a watchdog timer error may occur when the printer repeatedly enters/leaves the power saving mode.
		Fixed a bug below that occurs when multiple interfaces are selected: The CPU execution error occurs if connecting and disconnecting the USB cable after switching to rewriting preparation mode in Ethernet.
		Fixed a bug that Core1 does not return from the power saving mode with GS_I_1 command + Feed SW (sharing of countermeasure for defects in TM-H6000V).
Fixed a bug that a debugging error occurs if the printing and cutting operations are repeated in the Ethernet specification.		
Deleted the MAC address of Wi-Fi from the self-test printing, because the printer cannot recognize the Wi-Fi dongle correctly.		
3.20A ESC/POS 3.20B ESC/POS	Changed function	Supported OT-WL: Ver. 3.20A : OT-WL02/WL06 Ver. 3.20B : OT-WL05/WL06 * The OT-WL06 is supported in certain regions.
		Changed default password for WebConfig access from "epson" to the serial number of the printer to comply with the regulations (Chapter 886) in California, U.S.
		Changed contents of the self-signed certificate to comply with the iOS 13 specifications.
	Bug fix	Fixed a bug that unnecessary ASB is sent when opening the cover during printing.
		Fixed a problem that the position is shifted from the middle of the image with ePOS Print.
		Fixed a bug that the network response time slows down when a large number of UDP packets are received at startup.

3.21A ESC/POS 3.21B ESC/POS	Changed function	Supported OT-WL06. * The OT-WL06 is supported in certain regions.
		Improved a connectivity to AP (SSID is in stealth mode) with W53/W56 when using OT-WL06.
		Changed the SNMP packet processing during the power saving mode.

* Ver. **. **A ESC/POS supports OT-WL02 and OT-WL06.

* Ver. **. **B ESC/POS supports OT-WL05 and OT-WL06.