

Firmware Change History for TM-T810F

Version	Category	Detail
1.01 ESC/POS	Changed function	Measures to prevent missing dots caused by Over energy.
		Added support for new ROM to deal with EOL of the current serial flash ROM.