

Firmware Change History for TM-T81II (Ethernet model)

Version	Category	Detail
7.04 ESC/POS	Changed function	Measures to prevent missing dots caused by Over energy. Added support for new ROM to deal with EOL of the current serial flash ROM.