

Firmware Change History for TM-T82 (Ethernet model)

Version	Category	Detail
2.11 ESC/POS	Changed function	Measures to prevent missing dots caused by Over energy