

Firmware Change History for TM-T83II

| Version | Category | Detail |
|--------------|------------------|--|
| 5.02 ESC/POS | Changed function | Measures to prevent missing dots caused by Over energy that will shorten the Print head life |
| | Bug fix | Fixed a bug that QR codes/graphics are printed in mangled when the USB I/F disables the flow control |