

Firmware Change History for TM-T60 (Ethernet model)

Version	Category	Detail
2.01 ESC/POS	New Release	-
2.02 ESC/POS	Changed function	Measures to prevent missing dots caused by over energy. Added support for a new flash ROM to deal with EOL of the current one.