

### Firmware Change History for TM-T60 (USB model)

Version	Category	Detail
1.02 ESC/POS		Measures to prevent missing dots caused by over energy.
	Changed function	Added support for a new flash ROM to deal with EOL of the current one.
	Bug fix	Fixed a bug that QR codes/graphics are printed in mangled when the USB I/F disables the flow control.